Page 1 of 6



# TENNESSEE DEPARTMENT OF TRANSPORTATION EROSION PREVENTION/SEDIMENT CONTROL INSPECTION REPORT

Reason For Inspection:

Predicted Precipitation Source:

1st Weekly

2nd Weekly

											DATE:	27:11		
State Route	(SR) / US Rou	ite or Road Na	ame and De	escription:	-		Are correct	ive actions	required by	this inspec	ction report (Y/N):			
		WolfI	River Blvd.						/	NO				
County(ies):		TDOT PIN:		NPDES Pe	rmit (NOC)	#:	Number of	New	Number of	Recurring	Number of New	Number of Un-Corrected		
5 4 4	nelby	1016			NR153299		Corrective /	Actions:	Corrective A	Actions:	Sediment Releases:	Sediment Releases:		
		TDOT Contra	ct No.:	Contractor:					40			0		
	1535-54			Acuff	Enterprises	s Inc.	Ö		0		O	U		
											Io:			
	er penalty of law ler my direction of					Consultant	EPSC Insp	ector and I	ille (print or	type):	Signature:	11 / 1		
designed to a information p	issure that qualif resented. Based	fied personnel p d on my inquiry	oroperly gath of the perso	ered and eva	aluated who			erald Stanf	*		Derahl	Zerahl Stamiil		
	system, or those cerify that inspe					Contractor	EPSC Insp	ector and T	itle (print or	type):	Signature:	0/00		
above. I cert	d sediment contri ify that erosion a	and sediment co	ontrols in the	drainage are	ea of the	Tom Acuff					Jam levell			
	fall where installe ne table above. I					TDOT Project Supevisor / Designee and Title					Signature:			
	se information, i					(print or ty				<del>(1000 - 1000)</del>	1	01		
knowing viola	itions.					Michael Rebick								
		TDOT EPSO	Inspectio	n Weekly R	Rainfall Dat	a Log								
		Predicted	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall			ntractor Agrees with Ir	spection Report:		
Date	Day of Week		Gauge 1	Gauge 2	Gauge 3	Gauge 4	Gauge 5	Gauge 6	Duration	NO	or YES			
		(%)	(in)	(in)	(in)	(in)	(in)	(in)	(hr)	If No, expl	ain and initial:	April 1		
3.20:11	Sunday	10		noice and a second	N/A	N/A	N/A	N/A				VI 2 (VI ) CONT (CIN )		
3,21.11	Monday	0	0	0	N/A	N/A	N/A	N/A						
3.22111	Tuesday	10	0	0	N/A	N/A	N/A	N/A						
3:23.11	Wednesday	10	0	0	N/A	N/A	N/A	N/A						
3.24111	Thursday	0	0	0	N/A	N/A	N/A	N/A						
3.25.11	Friday	30			N/A	N/A	N/A	N/A			No.	7 A		
3,26,11	Saturday	60			N/A	N/A	N/A	N/A						
3.27.11	Sunday	30			N/A	N/A	N/A	N/A						
3,28,11	Monday	30			N/A	N/A	N/A	N/A						
			-					ar de al disse de		(Add	ditional pages may be	attached, if needed)		

. www.weather.com

OF THE ST
ACRICUITURE
1796

State/US	Route	or Road	Nama.
State/US	Route	UI KOAU	Maille.

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

CONDITION CODES

Date 3,24-11

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stablilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1A	1	21+50	RT				5	NO CURRENT ACTIVITY
1B	1	22+00	RT			=	5	NO CURRENT ACTIVITY
1C	1	21+00	LT	3.23.11		24, 33	FM	STABILIZE DISTURBED AREAS WITHIN IS DAYS
2A	1	33+50	LT	3.23.11		33	FM	STABILIZE DISTURBED AREAS WITHIN 15 DATS
2B	1	35+50	LT				5	NO CURRENT ACTIVITY
3	1	34+50	LT				5	NO CURRENT ACTIVITY
4	1	40+00	RT				5	NO CURRENT ACTIVITY
5A	1	49+00	RT				5	NO CURRENT ACTIVITY
5B	1	50+00	RT				5	NO CUPPENT ACTIVITY

### **EROSION AND SEDIMENT CONTROL MEASURE CODES**

### Temporary Silt Fence / Filter Barrier Excess Dirt Removed from Rdwy. Daily Temporary Seeding with Mulch 29 Temporary Diversion Berm or Ditch 30 Haul Roads Dampened for Dust Control 16 Temporary Mulch Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 31 Ditch Liner Erosion Control Blanket R Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance 5 Brush Barrier Temporary Silt Fence with Backing 19 Chatch Basin / Storm Inlet Protection 33 C Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures 7 Straw Bale Check 21 Sediment Tube Riprap Energy / Velocity Dessipater 35 W Too Wet to Work Condidtions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues Sediment Release SR Temp Sediment Filter Bag / Dewatering 10 24 **Temporary Stream Crossing** 38 Berm (soil, reprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone Other (O#2): 41 14 Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade Other (O#3): 42

OF THE SO	
ARE	
AGRICULTURE	
1796 - 3	

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:
			1000100101	155, 55,11,150,110.

Date 3,24,//

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stablilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
5C	1	44+00	LT				5	NO CURRENT ACTIVITY
6	1	56+00	LT				5	NO CURRENT ACTIVITY OUT FALL STABLE NO CUPRENT ACTIVITY
7	1	60+00	RT				5	NO CURRENT ACTIVITY
8A	1	73+00	RT				5	NO CURRENT ACTIVITY
8B	2	75+50	RT				5	NO CURRENT ACTIVITY
8C	1	71+00	LT				5	NO CURRENT ACTIVITY
8D	2	75+50	LT				5	NO CURRENT ACTIVITY
8E	1	71+50	LT				5	NO CURRENT ACTIVITY
9A	2	80+00	RT				5	NO CURRENT ACTIVITY
9B	2	80+00	LT				5	NO CURRENT ACTIVITY

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

### Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy. Daily 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner R Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance Chatch Basin / Storm Inlet Protection 5 Brush Barrier 19 33 Temporary Silt Fence with Backing C Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 **Enhanced Silt Fence** Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dessipater 35 Sediment Tube W Too Wet to Work Condidtions Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering Temporary Stream Crossing Berm (soil, reprap, rock) 24 38 Final Stabilized Polyethylene Sheeting 11 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) Machined Rip Rap 12 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): Other (O#2): 13 Geotextile Preserve Natural Resource / Buffer Zone 27 41 14 Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Subgrade 42 Other (O#3):

**CONDITION CODES** 

نزد.	THEST	
67	THE STATE OF	
3 ^	GRICULTURE	
181	OMMEN (S)	
	1796 3	

State/US	Danta as	Dood	Mana
State/US	ROHE OF	KOMU	Name.

Wolf River Blvd. TDOT Construction No.: 79954-3537-54

TDOT Contract No.:

**CONDITION CODES** 

Date 3,24.11

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stablilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT				5	NO CURRENT ACTIVITY
10A	2	85+00	RT				5	NO CURRENT ACTIVITY
10B	2	85+00	RT				5	NO CURRENT ACTIVITY
10C	2	85+50	LT				5	OUT FALL STABLE NO CURPENT ACTIVITY OUT FALL STABLE
10D	2	84+50	LT				5	NO CURPENT ACTIVITY
11A	2	92+50	RT				2	NO CURRENT ACTIVITY
11B	2	92+50	LT				5	OUTFALL STABLE NO CURRENT ACTIVITY
11C	2	92+00	LT				5	NO CURRENT ACTIVITY
	12							

# **EROSION AND SEDIMENT CONTROL MEASURE CODES**

1	Temporary Silt Fence / Filter Barrier	15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy, Daily		
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Chatch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dessipater	35	Sediment Tube	W	Too Wet to Work Condidtions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, reprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	s	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	•
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41		Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42		Other (O#3):	



# State/US Route or Road Name: MOLF RIVER BLUD TDOT Construction No.: 79954 - 3537 - 54

TDOT Contract No	o.:	

**CONDITION CODES** 

Date 3:24://

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stablilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
0A	1	11+28	LT			19	5	TEMP EPSC MEDSURES FNSTAUED
0B	1	12+80	RT			19	S	TEMP. EPSC MEASURES TUSTAUED
0C	1	12+90	LT			19	5	TEMP. EPSC NAEASURES PNSTALLED
0D	1	108+00	LT			19	5	TEMP ERSC MENSURES INSTALLED
OE	1	108+10	255' RT of CL along N. curb line of Farmington Blvd.			19	5	TEMP. EPSC MEASURES  INSTALLED
OF	1	13+40	RT			23	5	CONST, EXIT/ENTRANCE STABLE NO CURRENT ACTIVITY
1	1	14+14	LT				5	NO CURRENT ACTIVITY
1	1	1/+28 -12+80	LT		3,21.11	22	5	NO CURRENT ACTIVITY
				•				

# **EROSION AND SEDIMENT CONTROL MEASURE CODES**

1	Temporary Silt Fence / Filter Barrier	15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily		
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Chatch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	C	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dessipater	35	Sediment Tube	W	Too Wet to Work Condidtions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, reprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	•
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41		Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42		Other (O#3):	



Outfall 1C Sta. 21+00 LT Stabilize disturbed areas within 15 days.



Outfall 2A Sta. 33+50 LT Stabilize disturbed areas within 15 days.



City of Germantown 1920 S. Germantown Road Germantown, TN 38138